

North Las Vegas - VGT

ATIS – (702) 631-7125

Average Daily Operations – 635

Normal Operations – Runway 7


For more information about this airport contact:

Tower (702) 261-3802 – Airport (702) 648-6588

www.mccarran.com/nlva.htm

Runway 12 and Taxiway A1

Aircraft taxiing northeast bound on Taxiway A1 fail to hold short of runway 12. This may be due to the curve in this taxiway. Pilots must be very alert to avoid crossing the runway hold bars.



The airport operator has recently repainted the ramp area in the area of runway 07 and taxiway A1 and A2. This effort is very apparent to pilots and should assist pilots in remaining short of runway hold short lines.

Due to a continuing construction project on the airport adding a parallel runway to Runway 12/30 and a centerfield taxiway between the parallels, please check the North Las Vegas Tower or Runway Safety Program Office Web Page for airport updates.

Western-Pacific Region Runway Safety Program <http://www.awp.faa.gov/ops/awp600/runway> (View Hot Spots) or <http://www.awp.faa.gov> and proceed to the Runway Safety Link

